Troubleshooting
Guide

Doc No. 990674-6

## Mackworth TX Ceiling Lift Troubleshooting Guide **Scenario:**

Ceiling Lift does not traverse

REVISION. A

When operating the hand controls, the ceiling lift has power and performs the usual lifting and lowering actions, but does not respond to traversing commands. –Unresolved?→ spect the internal profile of the track to see i the wheels are spinning during traverse Retest the function by operating the hand commands. Inspect the track from any swarf, Retest the function by operating the hand debris or liquid that may be causing the slippage. YES/UNSURE-The handset traverse buttons on the air tubes may be damaged/leaking -Unresolved? -Unresolved?-Inspect the full length of the drive motor cables and connection points Unresolved? No. 990SD-09

