



Mackworth TX Ceiling Lift Troubleshooting Guide

Scenario: Ceiling Lift does not interact with auxiliary output

When operating the hand controls, the ceiling lift has power and performs the usual lifting and lowering actions, but does not respond to auxiliary output commands.



Key:

Question

Action

Component
Replacement

Supporting
Document

Additional Context
and Actions